

**COUNCIL MEETING AGENDA REQUEST FORM**

\*\*\*\*\*

COUNCIL MEETING DATE: May 12, 2026

SUBJECT/REASON FOR AGENDA ITEM: \_\_\_\_\_

Temporarily Alcohol Permit Waiver  | Open Container Law Waiver

Other: \_\_\_\_\_

*Please be specific about the reason to be on the agenda.*

Introduction of an ordinance to declare as surplus and authorize the sale of the items listed to sell on Govdeal.com

Requested By: Purchasing

NAME: Charles Borchers

Please note that the Hammond City Council meets the Second and Fourth Tuesday of the Month at 5:30pm, 312 East Charles Street, Hammond, LA 70401, All requests have to be submitted to the City Council Clerk by the Wednesday prior of the meeting no later than 4:30pm, All requests can be submitted electronically to cockerham\_lc@hammond.org or fax (985) 277-5611. If you have any questions please call (985) 277-5610

**BELOW TO BE FILLED OUT BY COUNCIL CLERK**

\*\*\*\*\*

DATE RECEIVED: \_\_\_\_\_ TIME RECEIVED: \_\_\_\_\_

Council Clerk: Lisa Cockerham Agenda Item Number \_\_\_\_\_

Approved: \_\_\_\_\_ (Yes) \_\_\_\_\_ (No)

Remarks: \_\_\_\_\_

Kip Andrews - Council President

\_\_\_\_\_  
Lisa Cockerham

\_\_\_\_\_  
Date

<b>UNIT</b>	<b>DESCRIPTION</b>	<b>MILEAGE</b>	<b>VIN</b>	<b>PROBLEMS WITH UNIT</b>
1006	2014 Expedition		1FMJU1F57EEF10921	Needs new Motor
	2013 DODGE CHARGER		2C3CDXBG7DH509903	No title due to vehicle being seized and a lien on it. Parts car only
600	2007 CHRYSLER	61,787	2C3LA43R77H603825	Obsolete components; A/C inoperative and cannot be repaired due to parts availability and needs a new transmission
995	2013 TAHOE	125,333	1GNLC2EOXDR259466	Needs new Motor
760	2009 CROWN VIC	94,229	2FAHP71V29X123689	Needs new Motor and wiring
242	2006 CADILLAC ESCALADE		1GYEC63T35R145407	Seizure, Inside destroyed and has been flooded
1099	2017 TAHOE	74,411	1GNCLEDCOHR159632	Damaged wiring harness; electrical issues front to back
1088	2016 TAHOE	108,614	1GNCLDEC5GR381453	Engine block cracked / thrown rod
1040	2011 CHEVROLET IMPALA		2G1WG5EK0B1244664	Seizure, Needs a new transmission and the interior needs replacing

994	2013 TAHOE		1GNLC2E02DR263107	Needs Motor
1044	2015 EXPLORER	106,678	1FM5K8AR7FGA94241	Needs Transmission and Catalytic Converter
976	2012 TAHOE	141,814	1GNLC2E08CR326841	Needs new Motor
1087	2016 TAHOE	160,417	1GNLCDEC2GR382737	A/C system inoperative and needs Motor
400	2008 WOODS BW 1800		1108510	Front tongue damaged; gearbox failure; deck/hull rusted; tires in poor condition; hub damaged
100	2015 HISUN UTV		LWGMDXZ07FA000050	All seats require replacement. The engine is misfiring and in poor condition. The transmission and rear differential both need replacement, and replacement parts are difficult to locate due to availability.
442	1999 DODGE RAM		3B6MC3657XM539143	Needs new motor
3705	9000 LB 2 POST AUTO LIFT		937250	Needs Safety Locks, Cylinder leaks will not meet/ pass code
567	2004 FORD F150		2FTRX17W44CA26683	Needs Motor

	2007 TAHOE		1GNFC13C57R372492	Needs new Motor and Transmission
592	2005 FORD F-250		1FTNF20595EB30803	Needs Motor, A/C system inoperative
7131	6X12 PULL TRAILER 3500 LB			Axle and tires missing; tongue bent; unit not operational
5288	TRAILER, LEAF DUMPING		16VDX102711E41941	
	4FT BUSH HOG			Gear Box Broke
	6FT BUSH HOG			Deck Rusted out and Gear Box Broken















































